Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	61	(72/342.92).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/09/06 10:07
L2	13	press and heater and form\$3 and (insul\$5 ADJ enclosure).CLM.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/09/06 10:08
L4	55	("3340101" "3516274" "3920175" "3927817" "3974673" "4087037" "4197977" "4233829" "4233831" "4266416").PN. OR ("4352280"). URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2006/09/06 10:10
S1	895	(72/60).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/09/05 16:07
S2	25	S1 AND insulation	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/14 09:59
S3	0	("00342.7").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/14 09:59
S4	103	(72/342.7).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/14 10:53
S5	0	S4 AND (Larson-Lowell.XP.)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/14 10:00
S6	94	(72/342.8).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR ·	OFF	2005/11/14 10:01

9/6/2006 10:12:35 AM
C:\Documents and Settings\dwolfe\My Documents\EAST\Workspaces\10788931 Heated & Insulated Tool Container.wsp Page 1

	1		 			
S7	12	S6 AND larson-low\$.XP.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/14 10:02
S8	· 60	(72/342.92).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/14 10:03
S9	8	S8 AND larson-low\$.XP.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/14 10:04
S10	10	S4 AND larson-low\$.XP.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/14 10:04
S11	7	("3934441" "4352280" "4901552" "4984348" "5209093" "5661992" "6253588").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2005/11/14 10:51
S12	408	(72/54).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/14 10:51
S13	9	S12 AND insulation	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/14 10:51
S14	83	(72/342.7).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/11/14 13:06
S15	70	(72/342.8).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/11/14 13:31
S16	47	(72/342.92).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/11/14 13:31
S17	252	(72/342.7-342.92).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/14 15:10

S18	0	S17 AND "load bearing spacer"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/14 15:10
S19	17	S17 AND spacer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/14 15:23
S20	22	S17 AND seal	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/15 06:57
S21	409	(72/38).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/11/15 06:57
S22	543	(72/38).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/18 06:55
S23	28	S22 AND insulation	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/15 07:19
524	81	S22 AND seal	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/15 07:19
S25	24	S22 AND seal AND insul\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/15 07:20
S26	543	(72/38).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/18 06:56
S27	13	S26 AND seal AND (press OR die) AND insulation	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2005/11/18 06:56
S28	1	("3551952").PN.	USPAT	OR	OFF	2006/04/18 13:56

Page 3

S29	909	(72/60).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO;	OR	OFF	2006/09/06 09:35
			DERWENT			

9/6/2006 10:12:35 AM C:\Documents and Settings\dwolfe\My Documents\EAST\Workspaces\10788931 Heated & Insulated Tool Container.wsp Page 4